Annexure D

BUILDING SAFETY CERTIFICATE

No. Dated: 14.07.2026

It is certified that the existing building Little Flowers School ...(name of the building or premises) at Pura., Babhnan - Basti

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1	–	–	–	–	–

The building is owned/occupied by.....Little Flowers School..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ..Rural Engg. Dept. (Name of Department/ Govt.) on...14.07.2026..(date of inspection) in the presence of Mrs. Kiran Singh (Manager), Pura Babhnan Basti (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..14.07.2026 for a period of .....10....., years in accordance with rule and subject to compliance of the specific conditions as appended.

1.
2.
3.
4.

Issued on ..14.07.2026..... at .....01:00 pm.... by

14/07/2026

Er. Amar Singh
Nagar Panchayat Harraiya
Mob.: 9838503733

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: _____

Name: AMAR SINGH

Designation: _____

Name & Address of Department/ Office: _____